

Supplementary Figure 1. EPI distortion due to the DBS electrode and Extension connector

(A) EPI distortion of the DBS electrode





(B) EPI distortion of the Extension connector

