**S3. Fig 2. Plotting graphs to determine the efficiency of Q3 plus and Step one.**

Description formula E = (10-1/slope − 1) x 100



Efficiency of 216%



Efficiency of 118%