

Erratum to: Ceramic Heads Decrease Metal Release Caused by Head-taper Fretting and Corrosion

Sevi B. Kocagoz BS, Richard J. Underwood PhD, Daniel W. MacDonald MS,
Jeremy L. Gilbert PhD, Steven M. Kurtz PhD

Published online: 8 March 2016
© The Association of Bone and Joint Surgeons® 2016

Erratum to: Clin Orthop Relat Res (2016) 474:985–994 DOI 10.1007/s11999-015-4683-1

In the study, “Ceramic Heads Decrease Metal Release Caused by Head-taper Fretting and Corrosion” there is an error in the Materials and Methods section regarding the second moment of area. The correct second moment of area is $I = \frac{\pi}{4} r^4$. The sentence should read: “The second moment of area $I = \frac{\pi}{4} r^4$ was determined using the radius of

the stem cone taper (r) at the distal end where the trunnion exits the bore.”

The authors apologize for the error.

In addition, the last sentence of the first paragraph in the Discussion section is missing a period. The sentence should read: “Visual fretting-corrosion scores were correlated with volumetric material loss.”

We apologize for the error.

The online version of the original article can be found under
doi:[10.1007/s11999-015-4683-1](https://doi.org/10.1007/s11999-015-4683-1).

S. B. Kocagoz, R. J. Underwood, D. W. MacDonald, S. M. Kurtz
School of Biomedical Engineering, Science, and Health
Systems, Drexel University, Philadelphia, PA, USA

R. J. Underwood, S. M. Kurtz
Exponent Inc, Philadelphia, PA, USA

J. L. Gilbert
Syracuse Biomaterials Institute and Department of Biomedical
and Chemical Engineering, Syracuse University, Syracuse, NY,
USA

S. B. Kocagoz (✉)
Implant Research Center, School of Biomedical Engineering,
Science, and Health Systems, Drexel University, 3401 Market
Street, Suite 345, Philadelphia, PA 19104, USA
e-mail: sk997@drexel.edu