



Cylinder

Stringiness



Low 0/10      Middle 5/10      High 10/10




Run#8      Run#60      Run#52

Infill



Low 0/10      Middle 4/10      High 10/10




Run#13      Run#10      Run#1

Fusion





Low 0/10      Middle 5/10      High 10/10




Run#57      Run#19      Run#25


Cube




Low 0/10      Middle 5/10      High 10/10



Run#45      Run#26      Run#43



Low 0/10      Middle 5/10      High 10/10



Run#52      Run#47      Run#51