



Supplementary 2. Histograms of the standard deviation of the shape changes over the course of treatment (i.e., inter-fractional shape changes) for the different ROIs. Each bar indicates the proportion of the surface area in the ROI that exhibits the corresponding uncertainty.