

Table S1. Subsequent programming changes during follow-up.

Programming at Implant (10 days from implant)	N (% of total)	N (pct) patients with any programming change during follow-up	Settings Adjusted	Any change	Most recent change before 6-month period	Most recent change	Most time spent in
Nominal	34.3%	33.2%	AV	86.8%	45.2%	77.7%	86.6%
			VV	11.2%	4.8%	8.8%	9.3%
			AV & VV	7.5%	1.5%	6.2%	4.1%
			Dyn. Delay	42.2%	18.6%	35.2%	
AV Adjusted	40.2%	39.0%	AV	92.5%	48.9%	83.4%	88.6%
			VV	8.9%	4.0%	6.8%	6.8%
			AV & VV	7.0%	1.5%	5.0%	4.6%
			Dyn. Delay	26.0%	9.5%	19.0%	
VV Adjusted	10.6%	36.4%	AV	83.6%	43.6%	75.5%	83.6%
			VV	14.1%	5.9%	10.5%	11.7%
			AV & VV	5.0%	1.4%	4.1%	4.7%
			Dyn. Delay	50.0%	25.5%	42.7%	
AV and VV Adjusted	14.9%	37.0%	AV	85.7%	45.7%	73.0%	78.1%
			VV	15.6%	5.1%	11.7%	11.9%
			AV & VV	16.5%	4.4%	11.4%	10.0%
			Dyn. Delay	34.3%	14.3%	27.0%	
Total	5709	36.4%	AV	88.8%	46.7%	79.2%	85.8%
			VV	11.2%	4.6%	8.6%	8.9%
			AV & VV	8.4%	1.9%	6.3%	5.3%
			Dyn. Delay	34.9%	14.8%	27.8%	

AV: atrioventricular timing; VV: ventricular-to-ventricular timing.