

Supplemental Digital Content 5: Location of femoral catheters and direct visualization of femur fracture from captive bolt stun gun. A 12Fr ECMO catheter is placed in the femoral artery and a 7Fr catheter is placed in the other femoral artery. A 10Fr catheter is placed in the femoral vein for resuscitation. The femur are fractured using a captive bolt stunner and direct visualization confirms femur fragmentation.

