SUPPLEMENTAL FIGURE 2: Column replacement is suggested when peak separation or peak quality declines. Chromatograms on a C12 column for the same serum sample ($^{\sim}65 \, \mu g/dL$) showing acceptable peak separation (top), declining peak separation (middle), and both poor peak quality and poor separation (bottom).

